



Improved Suzuki Swift axial joint

| Sidem-nr | brand | make | OE-nr |
|----------|--------|---------------------|-------------|
| 77115 | Suzuki | Swift IV (AZG, AZH) | 48830 68L00 |

Problem:

Early wear on the axial joint

Cause:

Small diameter of ball ($\text{Ø}22$) resulting in a high strain on the surface of the insert

Consequence:

Noise and play in the axial joint

Solution:

Increased diameter of the ballpin: $\text{Ø}25$

