



308 II (T9)
308 SW II

09/2013 - 06/2021
03/2014 - 06/2021



Ref.	Sidem Ref.	Description	OE-number	Measures	Ref.	Sidem Ref.	Description	OE-number	Measures
1	53068	stabilizer link	98 090 457 80	L:335	9	53975	TCA right wbj	98 203 815 80 S1	c:16.5
2	853450	strut mount	98 004 797 80	di:16	10	53976	TCA left wbj	98 005 966 80 S2	c:16.5
3	853451	bearing	98 175 924 80	do:126	11	53977	TCA right wbj	98 005 965 80 S2	c:16.5
4	353.037	steering rack gaiter	16 108 175 80	D:51 d:12 L:186	12	53683	ball joint	96 721 924 80	c:16.5
5	53730	tie rod end left	16 108 177 80	c:14.5 th:FM14X1.5R	13	853655	silentblock for TCA	96 760 321 80	di:14.3 do:43.4
6	53731	tie rod end right	16 108 178 80	c:14.5 th:FM14X1.5R	14	853656	silentblock for TCA	96 760 352 80	di:14.1 do:50.3
7	53119	axial joint	16 112 423 80	th:MM14X1.5R L:208	15	853658	silentblock for TCA	98 163 803 80	di:14.2 do:50
8	53974	TCA left wbj	98 203 816 80 S1	c:16.5	16	853321	mounting axle body	98 034 811 80	do:80