


ATECA (KH7,KHP)

04/2016 ->



Ref.	Sidem Ref.	Description	OE-number	Measures	Ref.	Sidem Ref.	Description	OE-number	Measures
1	63563	stabilizer link	5Q0 411 315 A	L:335	13	63735	tie rod end right	1K0 423 812 J S2	c:13.2 th:FM16X1.5R
2	837407	strut mount	5Q0 412 331 E	di:14.6 do:64.1 L:42	14	863650	silentblock for TCA	5Q0 407 182 A	di:12.1 do:40.1
3	837408	bearing	5Q0 412 249 F	di:74 do:127 L:38.6	15	863649	silentblock for TCA	5Q0 407 183 E	di:13 do:65
4	837409 KIT	strut mount kit	5Q0 412 331 E S1	di:15 do:127	16	57178	TCA left wbj	3Q0 407 151 E S2	c:15.4
5	302.235	steering rack gaiter	5Q0 423 831	D:54 d:16 L:191	17	57179	TCA right wbj	3Q0 407 152 E S2	c:15.4
6	302.131	steering rack gaiter	1K0 423 831 A	D:50 d:15 L:193	18	63586	ball joint left	1K0 407 365 C	c:15.4
7	63513	axial joint	561 423 810	th:MM16X1.5R L:330	19	63587	ball joint right	1K0 407 366 C	c:15.4
8	63730	tie rod end left	1K0 423 811 J S1	c:13.2 th:FM16x1.5R	20	63278	TCA left wbj	3Q0 407 151 E S1	c:15.2
9	63731	tie rod end right	1K0 423 812 J S1	c:13.2 th:FM16x1.5R	21	63279	TCA right wbj	3Q0 407 152 E S1	c:15.2
10	63022	tie rod left	561 423 810 S1	c:13.2	22	63588	ball joint left	3C0 407 365 B	c:15.2
11	63023	tie rod right	561 423 810 S2	c:13.2	23	63589	ball joint right	3C0 407 366 B	c:15.2
12	63734	tie rod end left	1K0 423 811 J S2	c:13.2 th:FM16X1.5R					