


COMBO Mk I (B)

07/1994 - 10/2001



2 809812



1 809810

1 809810



3 809813

-> CHAS V3023597 / CHAS V3037204 ->



4 809827

CHAS V3023598 - V3037203



4 809827



5 809403



7 809433 KIT



5 809403



6 809411



6 809411



MS



8 9932



8 9932

PS



9 9933



9 9933

-> CHAS V3023597, V4166925, V6066279



10 9930



10 9930

CHAS V3023598, V4166926, V6066280 ->



11 9934



11 9934

Ref.	Sidem Ref.	Description	OE-number	Measures	Ref.	Sidem Ref.	Description	OE-number	Measures
1	809810	stabilizer mounting	90 447 946	di:21.5	7	809433 KIT	strut mount kit	90 445 207 S1	di:12
2	809812	stabilizer mounting	90 445 100	di:14.1	8	9932	axial joint	26 030 411	th:FM14x1.5R L:310
3	809813	stabilizer mounting	90 445 101	di:14.1	9	9933	axial joint	26 032 284	th:MM14x1.5R L:281
4	809827	stabilizer mounting	90 539 057	di:14.2	10	9930	tie rod end	26 087 868	c:10.7 th:FM12x1.5R
5	809403	strut mount	90 445 207	di:35.5 L:40	11	9934	tie rod end	26 065 265	c:10.7 th:FM12x1.5R
6	809411	bearing	90 170 695	di:12.3 do:130.5 L:27					