



Improved tie rod end Audi, Skoda & Volkswagen




	SIDEM	TOEPASSING	N° OE
37630 R	tie rod end	Audi A4	4F0 419 811 E
		Audi A6	
		Audi A8	
		Skoda Superb	
		VW Passat IV/V	

PROBLEM

- Reduced lifetime


CAUSE

- Silent block tears out
- Silent block becomes softer during time



SOLUTION

- The silent block is replaced by a rigid connection



RESULT

- Longer lifetime
- No loss of steering accuracy

