



## Improved silent block Alfa Romeo

	SIDEM	APPLICATION	OE-NR.
35172	track control arm	Alfa Romeo GT, 156, 147	518 34 093
35173	track control arm		518 34 094
835613	silent block		part of

### PROBLEM



- The silent block makes a cracking noise which is troublesome and experienced up to the interior of the car.
- backlash on the silentblock



### CAUSE

- Due to the special design by OE of this silent block the sealing is very critical.
- When the sealing is not perfect the lubricant flows away and the rubber wears off which leads to backlash and cracking noises.



### SOLUTION

- An extra closing lip against the rotating inner bush results in a better sealing.
- Special synthetic grease is used which has an extremely water repellent effect.

### RESULT



- significant positive effect on longevity

